



Sierra Steering Column Switch Connections

26



WIPE/WASH
SWITCH
R.H.S.



DIP/INDICATOR
SWITCH
L.H.S.

NB. IF STALK SWITCH DOES NOT HAVE
HORN BUTTON, USE EXTENSION PB
WIRE SUPPLIED WITH HARNESS TO
A SEPARATE SWITCH.

FIG	3-4-B
DATE DRAWN	
DATE APPROVED	

STALK SWITCH CONNECTIONS.
VIEWED FROM BACK OF SWITCHES.
FORD SIERRA SWITCHES.

MOULDINGS VIEWED FROM CABLE ENTRY			
DRAWN	DATE	CHECKED	DATE
DWN	16-10-97		

M.E.S. UNITS 10.12
LADBROKE PARK IND. EST.
WARWICK, CV34 5AE

DRAWING W 5400014

SCALE
N.T.S.